

- 290045 Z At 30°-25'N - 144°-23'W while enroute Long Beach West bound reduced speed to 13 knots to **repair feed pump-corrected ETA Far East 092000Z**
- 12/2-1030 Diverted from Yokohama to Subic Bay -
- 12/8 STBD Boiler-2 water wall tubes leaking - 4 tubes blistered - 30% cap. of right ^{port} water
- 12/10 0900K STBD Boiler out, port boiler leaking, SOA 8.5 knots - 5 days, water supply at present consumption, posit. = 29°-06'N, 153°-18'E
- 12/13 1400I Arr. Yokosuka - undergoing repairs
- 1/9 1200 Repairs completed.
Anchored awaiting Berth (Approx 1/20)
ETD Yokohama - 1/31 for S.F.
- 1/31 Dep. Yokohama for S.F. - ETA - 2/14
Diverted to East Coast, ETA Canal Zone - 2/20
Rev ETA " " PM 2/31
- 2/21 Arr Canal Zone (transit)
- 2/22 0315 Dep Canal Zone for Davisville R.I. - ETA 2/27
- 2/27 1745 Arr Davisville - ETD 3/4 for Canal Zone**
- 2/28 0001 Com Voy NSA 9 / Along 2

