OCTOBER 22, 1943

FROM:

ENSIGN EDWIN ANTHONY GEHRING, U.S.N.R., COMMANDING OFFICER, NAVAL ARMED GUARD, (C/O ARMED GUARD CENTER, BROOKLYN, N.Y.) S.S. ABEL STEARNS, GROSS TONS 7176

TO:

108

THE VICE CHIEF OF NAVAL OPERATIONS

VIA:

THE PORT DIRECTOR, BOSTON, MASS.

SUBJECT:

REPORT OF VOYAGE, S.S. ABEL STEARNS FROM GLASGOW, SCOTLAND TO BOSTON, MASS.

REFERENCE:

(A) GENERAL INSTRUCTIONS FOR COMMANDING OFFICERS OF NAVAL ARMED GUARDS ON MERCHANT BHIPS, 1943, PARAGRAPH 4301.

1. IN ACCORDANCE WITH REFERENCE (A) THE FOLLOW-ING INFORMATION IS SUBMITTED:

(A) TYPE OF VESSEL: FREIGHTER (LIBERTY)

TYPE OF CARGO: BALLAST

OWNER OF VESSEL: U.S.WAR SHIPPING ADMINISTRATION

CHARTERED TO: OPERATORS - A.H.BULL & CO.

GENERAL AGENTS - U.S.LINES SUB-AGENTS - ANCHOR LINE

(B) PORT OF DEPARTURE: GLASGOW, SCOTLAND
DATE: OCTOBER 5, 1943
CONVOYED

SPEED (AVERAGE) - 8 1/2 KNOTS

NUMBER OF SHIPS IN ESCORT: MOST SEEN AT ANY
TIME - 9, 2 TUGS,
RESCUE SHIP.
PATROL AIRGRAFT SEEN

NUMBER OF SHIPS IN CONVOY: 77 ACCORDING TO CRUISING PLAN

PORT OF ARRIVAL: BOSTON, MASS. DATE OF ARRIVAL: OCTOBER 22, 1943

- (C) THIS VESSEL HAD NO CONTACT NOR ACTION WITH THE ENEMY.
- (D) THE VOYAGE WAS ROUTINE WITH THE EXCEPTION OF THE FOLLOWING:
  - 1) STORM, OCTOBER 7 TO 14; SEAS REACHED MOUNTAINOUS HEIGHT, WIND 70 TO 75 KNOTS; SHIP PITCHED
    AND ROLLED TO EXTREME; DECK PLATES CRACKED
    IN THREE PLACES (TO PRESENT KNOWLEGE); VIBRATION OF SCREW OUT OF WATER SPLIT BASE OF
    4"50 READY BOX, GALE RUINED ALL GUN COVERS.

(E) THE COMMERCIAL RADIO OPERATOR APPEARED TO CARRY OUT WARTIME RADIO INSTRUCTIONS FOR MERCHANT VESSELS, PAR-TICULARLY IN REGARD TO KEEPING INTERCEPTED MESSAGES CON-FIDENTIAL.

(F) 1. VENTILATION OF THE FORWARD MAGAZINE IS INADE-QUATE TO KEEP THE TEMPERATURE WITHIN A SAFE RANGE DURING WARN WEATHER.

2. QUARTERS, LOCKERS AND ESPECIALLY STORAGE

SPACE ARE CROWDED.

3. FOUR OF THE OERLIKON GUNS CAN BE TRAINED

ON PARTS OF THE SHIP.
4. STOPS ON THE 3"50 GUN PREVENT ADEQUATE COVER-AGE OF THE AIR (DEPRESSION RAILS WOULD CORRECT NUMBERS 3 AND 4).

5. THE ARMED GUARD PERSONNEL DOES NOT INCLUDE ADEQUATE RADIO COVERAGE BY THE COMMERCIAL A RADIOMAN.

RADIO OPERATOR IS EXTREMELY DIFFICULT.

6. THE INBOARD READY SERVICE BOXES AT NUMBER 3 AND 4 OERLIKON GUNS ARE SITUATED SO CLOSE TO "MONKEY ISLAND" THAT THEY SERIOUSLY INTERFERE WITH THE PASSAGE OF THE MATES AND CAPTAIN ACROSS THE UPPER BRIDGE.

7. THE NEED IS FEET FOR A LOCKER FOR SIGNALING EQUIPMENT (E.G. ALDIS AND MULTI-PURPOSE KIT) ON THE UPPER BRIDGE. ALSO THERE IS NO PYROTECHNIC LOCKER ABOARD.

8. TWO TARGET PRACTICE ROCKETS (RECEIVED IN GLASGOW FROM D.E.M.S. ON OCTOBER 1, 1943) WERE FIRED AS TESTS; THE FIRST STRUCK THE WATER IMMEDIATELY ADJACENT TO THE SHIP'S SIDE; THE SECOND CROSSED THE SHIP OVER NUMBER FOUR HATCH AND STRUCK THE WATER IMMEDIATELY ON THE OTHER SIDE.

(G) THE MASTER AND OFFICERS OF THE SHIP CARRIED OUT "WARTIME INSTRUCTIONS FOR UNITED STATES MERCHANT SHIPS". BLACKOUT REGULATIONS WERE RIGIDLY OBSERVED.

Reem 2055 27 OCT 1943

10UTE TO:- 23

DP File No. (SC) 43/GBel EDWIN A. GEHRINGO

ARMED GUARD COMMANDER

QS ABEL STEARDS NO. .... MD1/PD (LAK: mos) No.

Headquarters, First Naval District 150 Causeway Street, Boston, Mass. 25 October 1943.

The Port Director, N.T.S., Boston, Mass. The Vice Chief of Naval Operations.

1. Forwarded.

2. Necessary action will be taken on item (F).

celle

M. MILME Captain, USN(Ret.)