UNITED STATES COAST GUARD Captain of the Port San Francisco

Dete <u>11</u>	/8/43	Time o	f arrival 1500	Place	San Francis	ico Bey	
Vessel	Clarence	Darrow	ClassSter	m Ship Natio	nality Amer	dean	
Owners/Operators War Shipping Administration Master W. T. Glenn							
			REPAIRS TO R	ADIO APPARAT	<u>us</u>		
The repairs to radio apparatus are necessary as follows:							
Transmitter Not Tested							
	MASTER						
						ilian des ma b	
			DESCRIPTION OF			eilamon	
	itters:	150				A. F. Miller	
Number	1 :: Type	#- 100- AY	_ Manufactured	by Federal T	elagraph Co	Power 300 Wa	tts
	'poussal	E protect 2				00-454-500 Kcs.	
Number						Power	
		A / *					
Emerge						Power 200 Wa	
		小身是1200位第4点进 位				0-454-500 Kes.	
Lifebo						Power 5 Wat	
	Freque	ncy range	500 Kcs.	alibrated to	500 Kes.	2001. A	
Receiv	ers:	Type #	Manufactured	by Freq	uency range	Location	on
Number	1 ; 128-	AX F	ederal-ATelagra	ph Co. 15-650	O Kes.	Radio Room	1
Number	2 ; SIRF-		SCOTT Radio	80-550	O Keseg	Radio Room	
Number	3;	01022		1900-2400	00-Kes		
Number	4 ;	adadā silti Selecēti a		C STAN			
	oat ;					MI then to the	No.
Direct	ion Finde	r; 106-B	Federal Te	lagraph Go.	270-500 Ke	s. Chart Room	
Auto -	- Alerm;	101-B	Federal Te	lagraph co.		Radio Room	
				over)			

Rank Radio Electrican
By direction of the Captain
of the Port.
San Francisco

Copy to: Port Director

12th Naval District

Room 447 - Federal Office Building
Federal Communications Commission,

328 Custom House