

Flying Dragon

(25)

TIME	DATE	ACTIVITY
2115	11-16-68	DEP SAN FRAN WestB // TOTAL DELAY FOR EMERG REEFER MACH RPLS: 2 Days, 3 hrs + 15 mins // CONTRAC SHORT: 3RD ENGR // ETA YOKO 12-3 // DANANG // CAMRANH // UUNG TAU // SAIGON // SATTAP
	17.3	ARR YOKO
	12-6	DEP YOKO // ETA DANANG 12-13
	12-13	ARR DANANG
1800Z	12-16	DEP DANANG // ETA CAMRANH 17 // UUNG TAU // SAIGON
2200Z	12-17	ARR CAMRANH // LOST 27 hrs 18 + 20 REEF. UNIT Due to INABILITY of Reefer To maintain adequate Hatch Temperatures
1130Z	12-22	DEP CAMRANH // ETA UUNG TAU 12-22
0000Z	12-23	ARR UUNG TAU
	12-24	DEP UUNG TAU // SAIGON // SATTAP
1725	12-25	ARR SAIGON // SATTAP // S.F.

100-100000