

UNITED STATES COAST GUARD

SAN JUAN, PUERTO RICO

OFFICE OF
CAPTAIN OF THE PORTSan Juan, P.R.,
7 January 1942General Manager,
Lykes Bros. Steamship Co., Inc.,
San Juan, P.R.

Dear Sir:

In the case of the ~~SS AMERICAN PRESS~~ only, arriving on or about the 7th. January, 1942, that vessel may be moored as follows:

1. Vessel to be moored at Section BC, Pier No. 6, port side to, bow to the east, as near the end of the pier as possible.
2. There is to be no anchor out while vessel is moored to dock.
3. Use manila lines for mooring; do not use wires.
4. Sufficient watch is to be on deck and in the engine room so as to be able to move vessel away from wharf in case of emergency.
5. A qualified officer is to be on board the vessel at all times while she is moored to the dock so as to be able to move her away from the dock in case of an emergency.
6. Adequate steam pressure is to be maintained at all times while vessel is moored at the dock to enable her to leave the dock in case of emergency.
7. Ship's fire hose is to be connected up and stretched out so as to reach any part of the vessel.
8. Ship's fire pump to be warmed up at all times.

An officer representing the Captain of the Port will be on board as directed, to enforce the above.

Very truly yours,

FOR THE CAPTAIN OF THE PORT,

W. H. BARTON,
Commander, U.S.C.G.Copy to:
Commandant, 10th. NavDist.
Commandant, USCG., Washington, D.C.
Captain of Port - Officers Watch
Master,
File