

UNITED STATES COAST GUARD

RADIO SEALING REPORT

Captain of the Port

San Francisco

Date Aug. 23, 1943 Time of arrival 1410 Place San Francisco bay.
 Vessel CAPE NEWENHAM Class S.S. Nationality American
 Owners/Operators Maritime Commission Master T.M.Lewis

REPAIRS TO RADIO APPARATUS

The repairs to radio apparatus are necessary as follows; _____

Master

DESCRIPTION OF RADIO APPARATUS

Transmitters: Senior radio operator L.Winesky

Number 1 :: Type # ET-8010-CA Manufactured by RCA Power 200 Watts
 Frequency range 350-500 Kcs. Calibrated to 375-400-425-468-500 Kcs.

Number 2 :: Type # ET-8019-A Manufactured by RCA Power 200 Watts
 Frequency range 4100-23000 Kcs. Calibrated to 5520-98280-11040-12420-16560-22120 Kcs.

Emergency : Type # ET-8010-CA Manufactured by RCA Power 50Watts
 Frequency range 350-500 Kcs Calibrated to 375-400-425-468-500 Kcs.

Lifeboat :: Type # 168-B Manufactured by Federal Telegraph Co. Power 5 Watts
 Frequency range 500. Kc. Calibrated to 500 Kc. (fixed)

| Receivers: | Type # | Manufactured by | Frequency range | Location |
|-------------------|------------------|-----------------|---------------------------------------|-------------------|
| Number 1 ; | <u>AR-8503</u> | <u>RCA</u> | <u>15-600 Kcs.</u> | <u>Radio room</u> |
| Number 2 ; | <u>B</u> | <u>RCA</u> | <u>350-515-Kcs.</u> | <u>Radio room</u> |
| Number 3 ; | <u>SLR-F</u> | <u>Scott</u> | <u>80-550 & 1900-24000 Kcs.</u> | <u>Radio room</u> |
| Number 4 ; | <u>SLR-12-B</u> | <u>Scott</u> | <u>530-1600 & 5550-15600 Kcs.</u> | <u>Chart room</u> |
| Lifeboat ; | | | <u>270-520 Kcs.</u> | |
| Direction Finder; | <u>AR-8707-X</u> | <u>RCA</u> | <u>XXXX-</u> | <u>Chart room</u> |
| Auto - Alarm ; | <u>AR-8600-X</u> | <u>RCA</u> | | <u>Radio room</u> |

(Over)

Signal Apparatus:

Brief description Blinker and International flags.


Brief description of sealing operations:

I hereby certify that I have, in accordance with orders of the District Coast Guard Officer, 12th Naval District, sealed the radio apparatus of the above-named vessel. The seals used in sealing the apparatus are

and are not serially numbered.

Note any deficiencies observed or other remarks:

Provisions of section 3-A of directive 3001020 complied with.



Joseph C. Chambers
Signature

Cox'n

Rank or rating

Captain of the Port
San Francisco, California
(Date)

1. Forwarded for the information of the Commandant, U. S. Coast Guard.


A.R. Mortland
Signature

Rank LT. (jg)

By direction of the Captain
of the Port.
San Francisco.

Copy to: Port Director
12th Naval District
Room 447 - Federal Office Building
Federal Communications Commission,
328 Custom House