

UNITED STATES COAST GUARD  
Captain of the Port  
San Francisco

RADIO SEALING REPORT

Date 10/3/43 Time of arrival 2300 Place San Francisco Bay  
Vessel MERICOS H. WHITTIER Class S.S. Nationality AMERICAN  
Owners/Operators Tidewater Associated Oil Co. Master L.M. York

-----  
REPAIRS TO RADIO APPARATUS

The repairs to radio apparatus are necessary as follows; None. Radio Operator  
is proficient and can tune his transmitters on Emerg. Ant. Trans. tested O.K.

-----  
Master  
-----

DESCRIPTION OF RADIO APPARATUS

Transmitters: Senior radio operator R.P. Foley  
Number 1 :: Type # 147-M Manufactured by Federal Telegraph Co. Power 200 Watts  
Frequency range 375 - 500 kc. Calibrated to 375 400 425 468 500 kc.  
Number 2 :: Type # \_\_\_\_\_ Manufactured by \_\_\_\_\_ Power \_\_\_\_\_  
Frequency range \_\_\_\_\_ Calibrated to \_\_\_\_\_  
Emergency : Type # 147-M Manufactured by Federal Telegraph Co. Power 50 Watt  
Frequency range 375 - 500 kc. Calibrated to 375 400 425 468 500 kc.  
Lifeboat :: Type # BT-8026 Manufactured by RCA Power 5 Watt  
Frequency range 500 kc. Calibrated to 500 kc. only

-----  
Receivers:

	Type #	Manufactured by	Frequency range	Location
Number 1 ;	<u>117-C</u>	<u>Federal Telegraph Co.</u>	<u>16-530 kc.</u>	<u>Radio Rm</u>
Number 2 ;	<u>123-B</u>	<u>Federal Telegraph Co.</u>	<u>350 - 550 kc.</u>	<u>Radio Rm</u>
Number 3 ;	_____	_____	_____	_____
Number 4 ;	_____	_____	_____	_____
Lifeboat ;	_____	_____	_____	_____
Direction Finder;	<u>3-A</u>	<u>Federal Telegraph Co.</u>	<u>250-550 kc.</u>	<u>Chart Rm</u>
Auto - Alarm ;	<u>101-B</u>	<u>Federal Telegraph Co.</u>	_____	<u>Radio Rm</u>

(Over)



Signal Apparatus:

Brief description Blinkers and International Flags.


Brief description of sealing operations: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

I hereby certify that I have, in accordance with orders of the District Coast Guard Officer, 12th Naval District, sealed the radio apparatus of the above-named vessel. The seals used in sealing the apparatus are \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

and are not serially numbered.

Note any deficiencies observed or other remarks:

Provisions of Section 3-A of directive 3001020 complied with.


  
Joyce B. Throckmorton  
Signature

Sp3/C

Rank or rating

Captain of the Port  
San Francisco, California  
(Date)

1. Forwarded for the information of the Commandant, U. S. Coast Guard.

  
Signature H. Crain

Rank Lieut.  
By direction of the Captain  
of the Port.  
San Francisco.

Copy to: Port Director  
12th Naval District  
Room 447 - Federal Office Building  
Federal Communications Commission,  
328 Custom House