

UNITED STATES COAST GUARD

Captain of the Port

San Francisco

RADIO SEALING REPORT

Date 26 Feb. 1943 Time of arrival 0515 Place San Francisco Bay
 Vessel MERICOS H. WHITTIER Class S.S. Nationality AMERICAN
 Owners/Operators Tidewater Associated Oil Co. Master J. F. Humphreys

REPAIRS TO RADIO APPARATUS

The repairs to radio apparatus are necessary as follows; _____

No Repairs.

Master

DESCRIPTION OF RADIO APPARATUS

Transmitters:

Senior radio operator R. P. Foley

Number 1 :: Type # 147-M Manufactured by Federal Telegraph Co. Power 200 Watt
 Frequency range 375 - 500 kc. Calibrated to 375 400 425 468 500 kc.

Number 2 :: Type # _____ Manufactured by _____ Power _____
 Frequency range _____ Calibrated to _____

Emergency : Type # 147-M Manufactured by Federal Telegraph Co. Power 50 Watt
 Frequency range 375 - 500 kc. Calibrated to 375 400 425 468 500 kc.

Lifebeat :: Type # _____ Manufactured by _____ Power _____
 Frequency range _____ Calibrated to _____

Receivers:

	Type #	Manufactured by	Frequency range	Location
Number 1 ;	<u>117-C</u>	<u>Federal Telegraph Co.</u>	<u>16-530 kc.</u>	<u>Radio Room</u>
Number 2 ;	<u>123-B</u>	<u>Federal Telegraph Co.</u>	<u>350 - 550 kc.</u>	<u>Radio Room</u>
Number 3 ;				
Number 4 ;				
Lifebeat ;				
Direction Finder;	<u>3-A</u>	<u>Federal Telegraph Co.</u>	<u>250 - 550 kc.</u>	<u>Chart Room</u>
Auto - Alarm ;	<u>101-B</u>	<u>Federal Telegraph Co.</u>		<u>Radio Room</u>

Number 1 ; 117-C Federal Telegraph Co. 16-530 kc. Radio Room

Number 2 ; 123-B Federal Telegraph Co. 350 - 550 kc. Radio Room

Number 3 ; _____

Number 4 ; _____

Lifebeat ; _____

Direction Finder; 3-A Federal Telegraph Co. 250 - 550 kc. Chart Room

Auto - Alarm ; 101-B Federal Telegraph Co. Radio Room

(Over)

Signal Apparatus:


Brief description Blinkers and International Flags.

Brief description of sealing operations: Sealing intact from last previous port.

I hereby certify that I have, in accordance with orders of the District Coast Guard Officer, 12th Naval District, sealed the radio apparatus of the above-named vessel. The seals used in sealing the apparatus are _____

and are not serially numbered.

Note any deficiencies observed or other remarks:



Joyce B. Throckmorton
Signature

Sea. 1/C

Rank or rating

Captain of the Port
San Francisco, California
(Date)

1. Forwarded for the information of the Commandant, U. S. Coast Guard.


Signature A. R. Mortland

Rank: Ensign

By direction of the Captain
of the Port.

San Francisco.

Copy to: Port Director
12th Naval District
Room 447 - Federal Office Building
Federal Communications Commission,
328 Custom House