

TIME	DATE	ACTIVITY
1800	4-29-60	DEP Bangor WestB // TOTAL DELAY FOR CREW: 2 DAYS, 2 hrs & 45 mins. // CONTRACT SHORT: 13RD RATE & 13RD ENGR // ETA Subic 5-17 (DANANG 5-2 (TURBINE FEED PUMP TURBINE SHAFT SEIZED) ETA <sup>MIDWAY</sup> 5 <del>8</del> , DIVERTING FOR EMERG. FEED PUMP TURBINE SHAFT REPLACEMENT.
PM	5-7	ARR <sup>MIDWAY</sup> - DIVERTED FOR TURBINE SHAFT REPLACEMENT ETC & ETD 5-10
	5-10	COMP PRS -- AWAITING RELIEF MASTER
	5-13	MASTER -- HONO -- AWAITING TRANSIT TO VESSEL ETD WestB, INDEF
<del>1600X</del>	5-16	DEP MIDWAY WestB // ETA Subic 5-26 DANANG

