

12/8	0304	Arr. Seattle, scheduled to load Bangor on completion repairs
12/14	0400	Dep. Pier 91, Seattle //
12/14	0700	Arr. Bangor to load. // ETD 182000Z 1 RH 15.0K6 //
		ETA Yokohama, 020318Z 4 Jan. //
12/18	1215	Dep. Bangor West bound // (short 1 ord mate & 1 oiler)
12/21	0305Z	Ref. 180300Z 2 01 CIB shorten track, 41° 24' N1, 135 37 W 9, RH 15.0K6 // 020052Z 9 Jan. // via 34 00 N 7, 155 00 W 1, 23 17 46 Z 3 RH 15.0K6. etc. // ETA Yoko, 020052Z 9 Jan. RH 15.0K6
12/24		Storm invasion - 39° 35' N 4, 159° 00' W 5 RH, 15 020318Z 4 Jan. // ETA Yoko 020546 Z
12/30		Ref. 180300Z 1 Dec. 4 Rev. Diversion, 33°-34' N 3, 160°-52' E 4 - ETA 062201Z
12/30		Ref. 180300Z 2 Dec. 3 ETA adverse weather
12/30		To date. \$406,663.00: \$112,157.00 for current reactivations //
1/1		Ref. 180300Z 2 Dec. 4. Rev. Des. - SUBIC BAY //
1/7	0600	Arr. Subic Bay - awaiting to depart for Vietnam
		ETD fm Subic to Danang - 1/25
		Rev ETD RVN - indop

