

# HAMILTON Victory

(12)

TIME	DATE	ACTIVITY
1400Z	10-31-68	DEP DANANG // ETA S.F. 11-24 (REDUCED SPEED FEED PUMP PROBLEMS)
	11-6	DEPARTING TO <u>YOKOHAMA</u> - EMERG FEED PUMP PPRS <sup>ETA 11-8</sup>
1530Z	11-8	ARR YOKO FOR MAIN FEED PUMP PPRS
0330Z	11-15	Comp pprs + DEP YOKO // ETA S.F. 11-29 6 DAYS 12 HRS DELAY FOR PPRS
0704	11-29	ARR S.F. MOTBA-S TO DISC FOR ROS
0600	12-2	SHIFTED TO Pier 34-S, pprs ETC 12-6
2400	12-8	Term Voy NSA 14/APL 3
0001	12-9	COMM ROS 9015 <sup>bbt</sup> ON BOARD
0830	12-9	DEP S.F. Pier 34-S
1505	12-9	ARR SUISUN, NDRF. 9015 <sup>bbt</sup> ON BOARD

YTIVITOM