

TIME	DATE	ACTIVITY
0800	11/29	Dep. Yoko - had failure in forced draft blower fan bearings - both center & port - Est. 7 hrs. steaming time @ 5 Kts before failure - ship diverted by Naval Control of Shipping to Nagoya - failure happened 11/29 - 2100 - ship's posit. 33°-10'N - 137°-16'E // ETA Nagoya 11/30 - 1400 //
0900	12/6	Shutdown STBD Boiler due tube failure - no injuries - SOA 10 KTS - cooling boiler down for internal examinations & vprs. at 05 2300Z - EXP. resume speed at 060500Z - EST. 48 hrs. to cplt. //
1000	12/7	STBD Boiler repaired - SOA 14 KTS - early Light arrival //
	12/11	Arr. Cam Ranh Bay sailed 1/5/66 - Arr Saigon 1/6
0800Z	1/10	DEP. SAIGON - 15.0KG - TRANSIT SAIGON RIVER ETA 1020N3 1070 3E1 101230Z 1 DEP 1020N3 1070 3E1 101300Z 5 DI 15.0KG AND DIRECT ROUTES ETA PT PONO P.I. 130000Z //

[Faint, illegible handwriting on lined paper]

[Faint, illegible handwriting at the bottom of the page]