

From: Armed Guard Commander of SS ABANGAREZ
To: The Vice Chief of Naval Operations.

VIA: The Port Director, Third Naval District.

4538
WT

Subject: Report of Structural Test Firing
of Guns Installed on the SS ABANGAREZ

Date of Firing: APRIL 2, 1943 No. of Rounds: 5 Elevations: 5-30°

Gun 3" 50 Installed: New York Location of Gun: Bow

TEST FIRING: Satisfactory YES
Misfire NONE (Report Below)

RESULTS OF FIRING:

Effect on Gun Mounts: NONE

Effect on Vessel: NONE

Gun _____ Location of Gun: _____

TEST FIRING: Satisfactory _____
Misfire _____ (Report Below)

RESULTS OF FIRING:

Effect on Gun Mounts: _____

Effect on Vessel: _____

REPORT OF MISFIRING (describe misfiring - explain probable cause)

1st Endorsement
Port Director, Third Naval District
17 Battery Place, New York, N.Y.

A9/DHq-84
RESTRICTED

May 3, 1943 1942
~~XXXX~~

From: The Port Director, Third Naval District.
To: The Vice Chief of Naval Operations.

- 1. Forwarded.

LES
L5
AGD

F. G. REINICKE,

Copies to: BuShips
BuOrd

By G. E. Stoddard
G. E. STODDARD
LT. (JG) USNR
Ordnance Materiel

DECLASSIFIED
Authority 750161