

RADIO SEALING REPORTUNITED STATES COAST GUARD
Captain of the Port
San Francisco

I.O.F.

Date 21 Sept. 1943 Time of arrival New Ship Place 1943 SEP 27 AM 10 11
San Francisco Bay
Vessel CHARLES E. SMITH Class S.S. Nationality AMERICAN
Owners/~~OPERATOR~~ W.S.A. Master LLOYD DAVID

REPAIRS TO RADIO APPARATUS

The repairs to radio apparatus are necessary as follows; _____

NONE

Master _____

DESCRIPTION OF RADIO APPARATUSTransmitters:Senior radio operator L. BYRNE

Number 1 :: Type # ET-8024 Manufactured by RCA Power 200 Watt
Frequency range 350 - 500 kc. Calibrated to 355 375 400 410 425 454 468 500 kc.
Number 2 :: Type # _____ Manufactured by _____ Power _____
Frequency range _____ Calibrated to _____
Emergency : Type # ET-8025 Manufactured by RCA Power 50 Watt
Frequency range 350 - 500 kc. Calibrated to 355 375 425 454 500 kc.
Lifeboat :: Type # ST-5M Manufactured by Technical Radio Corp. Power 5 Watt
Frequency range 500 kc. Calibrated to 500 kc. only

<u>Receivers:</u>	<u>Type #</u>	<u>Manufactured by</u>	<u>Frequency range</u>	<u>Location</u>
Number 1 ;	<u>AR-8510</u>	<u>RCA</u>	<u>16-650 kc.</u>	<u>Radio Rm</u>
Number 2 ;	<u>C</u>	<u>RCA</u>	<u>350 - 515 kc.</u>	<u>Radio Rm</u>
Number 3 ;	<u>SIR-F</u>	<u>Scott</u>	<u>80-550 & 1900-24000 kc.</u>	<u>Radio Rm</u>
Number 4 ;	<u>SIR-12-B</u>	<u>Scott</u>	<u>540-1600 & 5550-15600 kc.</u>	<u>Chart Rm</u>
Lifeboat ;	_____	_____	_____	_____
Direction Finder;	<u>AR-8709</u>	<u>RCA</u>	<u>260-540 kc.</u>	<u>Chart Rm</u>
Auto - Alarm ;	<u>AR-8601</u>	<u>RCA</u>	_____	<u>Radio Rm</u>

(Over)

Signal Apparatus:

Brief description Blinkers and International Flags.

Brief description of sealing operations:

I hereby certify that I have, in accordance with orders of the District Coast Guard Officer, 12th Naval District, sealed the radio apparatus of the above-named vessel. The seals used in sealing the apparatus are

and are not serially numbered.

Note any deficiencies observed or other remarks:

Provisions of Section 3-A of directive 3001020 complied with.

Joyce B. Throckmorton
Joyce B. Throckmorton
Signature

Sp3/C

Rank or rating

Captain of the Port
San Francisco, California
(Date)

1. Forwarded for the information of the Commandant, U. S. Coast Guard.

H. Crain
Signature H. Crain

Rank Lieut.
By direction of the Captain
of the Port.
San Francisco.

Copy to: Port Director
12th Naval District
Room 447 - Federal Office Building
Federal Communications Commission,
328 Custom House