Address Reply To District Engineer, U.S. Engineer Office, P.O. Box 5180 - Metro. Station, Los Angeles 55, Calif."

## Reply Reference: PALGB

## WAR DEPARTMENT UNITED STATES ENGINEER OFFICE 751 SOUTH FIGUEROA STREET LOS ANGELES, CALIF.

13 February 1946

P

Y

25750 Oil Pollution, Los Angeles Hapbor, 31 December 1945 assessing the

TO:

SUBJECT:

Commanding Officer

USS COMFORT c/o Postmaster San Pedro, California

Report has been received by this office that on 31 December Dear Sirs 1945 the USS COMFORT polluted the navigable waters of the United States with oil in the vicinity of Barth 88, Los Angeles Harbor. This is a violation of the Federal Oil Pollution Act of 7 June 1924 (33 U. S. Code, Sections 431-437) as well as State law and local regulations. A copy of this report is inclosed for your information. witnesses to the spill, no

15

2. Because of the great danger to commercial shipping and harbor facilities involved in pollution violations, the District Engineer facilities involved in policitudes of this offense. desires to emphasize the seriousness of this offense.

Particular attention is directed to Section 17 of River and Earbor Act, approved 3 March 1899, relative to the protection and preservation of the navigable waters of the United States and the responsibility of Officers and Agents of the United States in charge of river and harbor improvements. (See extract herewith inclosed.)

4. A supply of booklets and notices prepared by this office concerning the prevention of pollution of the navigable waters of the United States and the laws pertaining to violations thereof are inclosed, and it is requested that copies be furnished to responsible orew members in order that they may be thoroughly informed as to the laws and, therefore, govern themselves accordingly.

1. Copy of report dated 2. Copy 1 FOR THE DISTRICT ENGINEER:

G. B. BEBOUT co: District Coast Guard Officer (In dup.) Chief, Engineering Division

4 Inclosures (In dup.)

1. Copy report dated 4 January 1946

2. Extract R & H Act

3. Pociaion Booklets

4. Poliuvion Notices

cc: The District Coast Guard Officer (IN dup.)

Oress Reply To Ostrict Engineer, U.S. Engineer Office, O. Box 5180 - Metro. Station, Los Angeles 55, Calif."

## WAR DEPARTMENT UNITED STATES ENGINEER OFFICE 751 SOUTH FIGUEROA STREET LOS ANGELES, CALIF.

Reply Reference: PALGB

13 February 1946

0

P

Y

SUBJECT: (

Oil Pollution, Los Angeles Harbor, 31 December 1945 (USS COMFORT-United States Navy)

Subj: Report of Oil Spill from USS COUPURT, 31 December, 1915; formarding of

9 January, 1944

TO:

The United States Attorney Federal Building Los Angeles 12, California

Bub Dear Sir: the forwarded in compliance with instructions set forth in

Report of the above pollution case has been received from the District Coast Guard Officer, Long Beach 2, California, duplicate copies of which are inclosed for your information.

Inasmuch as there were no Federal witnesses to the spill, no physical evidence was obtained, and the oil dispersed rapidly due to the out-going tide, prosecution is not recommended.

Copies of all letters pertaining to the case are inclosed for your files.

FOR THE DISTRICT ENGINEER:

Very truly yours,

G. B. BEBOUT Chief, Engineering Division

3 Inclosures (In dup.)

1. Copy of report dated 4 January 1946

2. Copy ltr. to CO USS COMFORT

3. Copy ltr. to District Coast Guard Officer

cc: District Coast Guard Officer (In dup.)

## UNITED STATES COAST GUARD



LONG BEACH 2. CALIFORNIA

ADDRESS REPLY TO DISTRICT COAST GUARD OFFICER ELEVENTH NAVAL DISTRICT (1) REFER TO FILE: 661

9 January, 1946

To: The Commandant

Subj: Report of Oil Spill from USS COMFORT, 31 December, 1945; forwarding of

Subject report is forwarded in compliance with instructions set forth in Headquarters letter of 26 October, 1945. Original copy of same was forwarded to the U.S. Army District Engineer, Los Angeles, this date.

EDWIN S. CAMPBELL By direction Thitney, And the Engineering ( will was faused by oil siphoning through went on Tank 507F, on the star-

Incl Oil spill report on USS COMFORT (1/4/46)

3. Engineering Officer, Lt. Stuckrath, stated the spill was caused by ship's gangway catching on to the dock offing and then slipped, causing ship to lurch auddenly to starboard. Tank 507F which was already full and secured, bubbled up through vent and spilled into harbor. UNITED STATES COAST GUARD ELEVENTH NAVAL DISTRICT Wilmington, California

Address reply to THE CAPTAIN OF THE PORT LOS ANGELES REFER TO FILE: 629.1

GOPY

4 January, 1946

To: DCGO, 11ND

Subj: Oil spill; USS COMFORT, 31 December, 1945

1. At approximately 1235, 31 December, 1945, NFA, San Pedro, advised COTPLA of an oil spill while bunkering the USS COMFORT, Berth #88, San Pedro.

2. Investigation by COTPLA Oil Pollution Detail was made and report of investigation showed that the Commanding Officer was Captain Rintoul T. Whitney, and the Engineering Officer was It. Edward Stuckrath. The spill was caused by oil siphoning through vent on Tank 507F, on the starboard side of ship, while loading Special Nava Fuel bunkers. An area of approximately 100 feet by 10 feet was covered. Tide was going out, and oil dispersed rapidly.

3. Engineering Officer, Lt. Stuckrath, stated the spill was caused by ship's gangway catching on to the dock paling and then slipped, causing ship to lurch suddenly to starboard. Tank 507F which was already full and secured, bubbled up through vent and spilled into harbor.

/s/ G. B. GELLY