RADIO SEALING REPORT Captain of the Pert San Francisco

Date 10/17/42 Time of arrival 1: P.M.	Place San Franciaco Bay
Vessel FORT LEARD Class S.S.	Nationality BRITISH
Owners/Operators Salverena	Master Howe
REPAIRS TO RADIO APPARATUS	
The repairs to radio apparatus are necessary as follows;	
	Master
DESCRIPTION OF RADIO APPARATUS	
	radio operator Tilbrook
Number 1 :: Type #150-IIF Manufactured by Canadi	an Marconi Power 150 Watts
Frequency range 375 - 500 kc. Calibrated to 375 425 500 kc.	
Number 2 :: Type # TR-200 Manufactured by Cana	dian Marconi Power 200 Watts
Frequency range 6300 - 16845 kcCalibrated to 6300 8290 12845 16845 kc.	
Emergoncy: Type # Manufactured by Power	
Frequency range Calibrato	
Lifeboat :: Type #rg 5 B Manufactured by IMR	Power 50 Watts
Frequency range 500 kc. Calibrate	
Receivors: Type # Manufactured by	Frequency range Location
Number 1; MS1 - 5 Marconi	15 - 20000 kc. Radio Room
Number 2 ; DRD DRC	470 - 530 kc. Radio Room
Number 3 ; 3V Marconi	5000 - 18000 kc. Radio Room
Number 4;	
Lifoboat;	
Direction Finder; MFD - 5 Marconi	270 - 650 kc. Radio Room
Auto - Alarm; 8600 - X RCA	Radio Room
Auto Autom , 6000 - A nos	

and are not serially numbered.

Note any deficiencies observed or other remarks:

Robert G Behrens Signature

RMLC

Renk or rating

Captain of the Port Sen Francisco, California (Date)

1. Forwarded for the information of the Commandant, U. S. Coast Guard.

Signature W. P. Malloy

Rank Lt. (j.g.)
By direction of the Captain
of the Port.
San Francisco.

Copy to: Port Director
12th Naval District
Room 447 - Federal Office Building
Federal Communications Commission,
328 Custom House