SS FRANCIS C. HARRINGTON After the FRANCIS C. HARRINGTON struck a mine on Omaha Beach on 7 June, 1944, she suffered severe damage to her shaft. In this case, later publicized as "The ship with the wooden bearings", the Chief Engineer Singenuity, combined with the teamwork of his engine room crew, repaired the damaged ship with, among other things, wooden bearings for the shaft. These makeshift repairs enabled the ship to sail about 70 miles to safe harbor. the forward and of the sub, stripped of their belongings, includ-