

UNITED STATES COAST GUARD

Captain of the Port

San Francisco

RADIO SEALING REPORT

Date 25 Oct. 1942 Time of arrival 2:25 Pm Place San Francisco Bay
 Vessel Gulf Queen Class S.S. Nationality American
 Owners/Operators Gulf Oil Co. Master Fred. C. Burke

REPAIRS TO RADIO APPARATUS

The repairs to radio apparatus are necessary as follows; _____

None.

Master

DESCRIPTION OF RADIO APPARATUS

Transmitters: Senior radio operator J. Bettencourt

Number 1 :: Type # SE-842-C Manufactured by RCA Power 500 Watts.

Frequency range 375 - 500 Kcs. Calibrated to 375-400-410-425-454-468-500

Number 2 :: Type # _____ Manufactured by _____ Power _____

Frequency range _____ Calibrated to _____

Emergency : Type # ET-8003 Manufactured by RCA Power 50 Watts.

Frequency range 375-500 Kcs. Calibrated to 375-400-410-454-468-500 Kcs.

Lifeboat :: Type # _____ Manufactured by _____ Power _____

Frequency range _____ Calibrated to _____

Receivers: Type # Manufactured by Frequency range Location

Number 1 ; AR-8503 RCA 15-600 Kcs. Radio Room

Number 2 ; B RCA 350 - 515 Kcs. Radio Room

Number 3 ; _____

Number 4 ; _____

Lifeboat ; _____

Direction Finder; STD. Arrow Bludworth 270-425 Kcs. Chart Room

Auto - Alarm ; AR-8600-X RCA Radio Room

(Over)

Signal Apparatus:

Brief description Int. flags and Bliker

Brief description of sealing operations: Seals intact from last previous Sealing. Resealed Emergency due to unsatisfactory paper seal. Sealed Send-Receive switch in Receive position with ribbon and sealing wax.

I hereby certify that I have, in accordance with orders of the District Coast Guard Officer, 12th Naval District, sealed the radio apparatus of the above-named vessel. The seals used in sealing the apparatus are ribbon and sealing wax.

and are not serially numbered.

Note any deficiencies observed or other remarks:

Removed U.S. Customs paper seal #6087 as this particular type of seal has a tendency to come loose when subjected to heat and proved to be ineffective.

Charles T. Harris
Charles T. Harris
Signature

R.M.lc.
Rank or rating

Captain of the Port
San Francisco, California
(Date)

1. Forwarded for the information of the Commandant, U. S. Coast Guard.

W. P. Malloy
Signature W. P. Malloy

Lt. (Jg)
Rank
By direction of the Captain
of the Port.
San Francisco,

Copy to: Port Director
12th Naval District
Room 447 - Federal Office Building
Federal Communications Commission,
328 Custom House