

UNITED STATES COAST GUARD

RADIO SEALING REPORT

Captain of the Port

San Francisco

Date 10/5/43/ Time of arrival 1230 Place San Francisco, Bay
 Vessel Gulf Wave. Class S.S. Nationality American/
 Owners ~~W. J. W. W.~~ Gulf Oil Master H. Sorensen

REPAIRS TO RADIO APPARATUS

The repairs to radio apparatus are necessary as follows; Radio operator is
proficient and can tune emergency antenna OK. Tested OK.

Master

DESCRIPTION OF RADIO APPARATUS

Transmitters: Senior radio operator J. Cotty.
 Number 1 :: Type # ET-8006 Manufactured by RCA. Power 300 Watts
 Frequency range 375-500 kc. Calibrated to 375-425-468-500 kc.
 Number 2 :: Type # _____ Manufactured by _____ Power _____
 Frequency range _____ Calibrated to _____
 Emergency : Type # ET-8003 Manufactured by RCA. Power 50 Watts
 Frequency range 375-500 kc. Calibrated to 375-400-425-454-468-500 kc.
 Lifeboat :: Type # ET-8026 Manufactured by RCA. Power 5 Watts
 Frequency range 500 kc. Calibrated to 500 kc.

Receivers: Type # Manufactured by Frequency range Location
 Number 1 ; AR-8503 RCA. 15-600 kc. Radio Room/
 Number 2 ; B RCA. 350-515 kc Radio Room.
 Number 3 ; _____
 Number 4 ; _____
 Lifeboat ; _____
 Direction Finder; AR-8703 RCA. 270-520 kc. Chart Room/
 Auto - Alarm ; AR-8600-X RCA. Radio Room.

1 (Over)

Signal Apparatus:

Brief description Blinker and International Flags.

Brief description of sealing operations: _____

I hereby certify that I have, in accordance with orders of the District Coast Guard Officer, 12th Naval District, sealed the radio apparatus of the above-named vessel. The seals used in sealing the apparatus are _____

and are not serially numbered.

Note any deficiencies observed or other remarks:

Complied with directive 3001025, section 5-1.

Joseph S. Beckman
Joseph S. Beckman.

Signature

Sp. S/O.

Rank or rating

Captain of the Port
San Francisco, California
(Date)

1. Forwarded for the information of the Commandant, U. S. Coast Guard.

H. Chain
Signature H. Chain.

Rank *Lt.*

By direction of the Captain
of the Port.
San Francisco.

Copy to: Port Director
12th Naval District
Room 447 - Federal Office Building
Federal Communications Commission,
328 Custom House