

UNITED STATES COAST GUARD
Captain of the Port
San Francisco

RADIO SEALING REPORT

Date 17 June 1943 Time of arrival 0715 Place San Francisco Bay
Vessel HUGUENOT Class S.S. Nationality AMERICAN
Owners/Operators Richfield Oil Co. Master C. B. AUSTIN

REPAIRS TO RADIO APPARATUS

The repairs to radio apparatus are necessary as follows; _____

NONE

Master

DESCRIPTION OF RADIO APPARATUS

Transmitters: Senior radio operator R. W. DAVIS
Number 1 :: Type # ET-8010 Manufactured by RCA Power 200 Watt
Frequency range 375 - 500 kc. Calibrated to 375 400 425 468 500 kc.
Number 2 :: Type # _____ Manufactured by _____ Power _____
Frequency range _____ Calibrated to _____
Emergency : Type # ET-8003 Manufactured by RCA Power 50 Watt
Frequency range 375 - 500 kc. Calibrated to 375 400 425 468 500 kc.
Lifeboat :: Type # ET-8026 Manufactured by RCA Power 5 Watt
Frequency range 500 kc. Calibrated to 500 kc. only

Receivers:

	Type #	Manufactured by	Frequency range	Location
Number 1 ;	<u>AR-8503</u>	<u>RCA</u>	<u>15 - 600 kc.</u>	<u>Radio Room</u>
Number 2 ;	<u>B</u>	<u>RCA</u>	<u>350 - 515 kc.</u>	<u>Radio Room</u>
Number 3 ;				
Number 4 ;				
Lifeboat ;				
Direction Finder;	<u>AR-8700</u>	<u>RCA</u>	<u>270 - 520 kc.</u>	<u>NEEKS Chart RM</u>
Auto - Alarm ;	<u>AR-8600-X</u>	<u>RCA</u>		<u>Radio Room</u>

Signal Apparatus:


Brief description Blinkers and International Flags.

Brief description of sealing operations: Seals intact from last previous port.

I hereby certify that I have, in accordance with orders of the District Coast Guard Officer, 12th Naval District, sealed the radio apparatus of the above-named vessel. The seals used in sealing the apparatus are _____

and are not serially numbered.

Note any deficiencies observed or other remarks:


Joyce B. Throckmorton
Signature

Cox.
Rank or rating

Captain of the Port
San Francisco, California
(Date)

1. Forwarded for the information of the Commandant, U. S. Coast Guard.


Signature A. R. Mortland

Rank Ensign
By direction of the Captain
of the Port.
San Francisco.

Copy to: Port Director
12th Naval District
Room 447 - Federal Office Building
Federal Communications Commission,
328 Custom House