
## Declassified NARA Project: NW 63684

(Feb. 1943) NCG 924d-1 CONFIDENTIAL UNITED STATES COAST GO

UNITED STATES COAST GUARD
REPORT ON U. S. MERCHANT VESSEL WAR ACTION CASUALTY

TO: Commandant, U. S. Coast Guard, Washington, D. C.

Sh	ip S/S ISABELA	Servic	B 00E	AN FREIGHT	
Own	ner AGNILINES INC.	Operat	or AGH	ILLINES INC.	
In	fo. furnished by MASTER			Date 31 UULY 1944	
Line No. QUESTIONS		ANSWERS			
1.	Year built & propulsion	Built 191	1	Propulsion STEAM	
2.	Tonnage	Gross 310	9	Net /920	
3.	Draft loaded (max. allowed)	Fwd. 24'	(M)	Aft 17'10"	
4.	Draft when attacked	Fwd. 14 76'C	M)	Aft 17/10	
5.	Cargo on board (any deck)	Nature GEA	VERAL	Tons 1950	
6.	Voyage	From NEW	YORK	TO SAN JUAN P.R.	
7.	Were routing orders followed	YES	B1	prode & of homes I had	
8.	Any criticism of orders	No	franklit	Shadanes seem one of ad	
9.	Weather at time of attack	Weather CL	EAR	Sea MODERATE	
10.	Was enemy sighted - (when)	YES; AFTE	ER ATT	ACK	
11.	Any friendly ships in sight	No		brood an Lator 12a	
12.	Were navigation lights on	NO		A heart ware may at 32	
13.	Date and time of attack	Date 5/19/	42	Time 0445	
14.	Position	Lat.35 Mi	5 NAU	MASS A ISLAND LIGHT	
15.	Nature of attack (Give data)	TORPEDO	* SH	ELL THE THE PART OF THE PART O	
16.	Number of hits	I TORP.	; 7 SH	ELLS	
17.	Location of hits (Mark diagram)	1		VER-PORT-SIDE-AFT. 1-# 45	
18.	Effect of hits	SANK SHI	p	a continue and lead 1.69.	
19.	Was ship armed (What type)	No	172	. 50. Parsona lose by (Speci	
20.	Was armament used(State result)	NO			
21.	Any explosions or fires*	Ship No		Cargo No	
22.	Was deck ruptured	YES			
23.	Did ship break in two	NO		As payer amagazings	
	Was SOS sent	No			
	Ship's speed			cked 10 When abandoned STOP	
	Time abandoned, sunk		5 min.)	Sunk 0515 (30min.)	
	Was ship reboarded	By whom	NO	When —	
	Was ship brought in	How A	10	Approx. damage SUNK	



\*Fill in this diagram
to show attack hits,
fires, etc.

## Declassified NARA Project: NW 63684

## Sheet 2 NCG 924d-1

Indicate by star (\*) rafts, floats or suits used as temporary refuge in water before rescue by lifeboats

Line N	QUESTIONS	ANSWERS				
29.	Lifeboats	No.carried 4 Which used 2				
30.	Lifeboats	No. lost 2 How TORP, EXPLOSION				
31.	Life rafts	No.carried 4 Which used 3 *				
32.	Life rafts	No. lost / How TORP. EXPLOSION				
33.	Life floats	No.carried o Which used o				
34.	Life floats	No.lost o How o				
35.	Lifesaving suits	No.carried 38 No.used O				
36.	Were boats, etc. attacked	Attacked No Casualties O				
37.	Time in each boat, raft etc.	Boat 30 HRS. Raft Float				
	18	Boat 18 HRS Raft Float  MADE PORT TILERON				
38.	Rescued by & where	By MADE PORT Where IRIS, HAITI				
39.	No.gun crew carried (military)	Officers o Enlisted men o				
40.	No. ship's crew carried	Officers & Radio men / Unlicensed 28.				
41.	No.passgrs. & others carried	Passgrs. O Others O				
42.	Total on board	37 this all spirit tilbrein val. II				
43.	No.gun crew injured (military)	Officers O Enlisted men 6				
44.	No.ship's crew injured	Officers 4 Radio men / Unlicensed 3				
45.	No.passgrs. & others injured	Passgrs. O Others O				
46.	No.gun crew lost(military)	Officers o Enlisted men o				
47.	No.ship's crew lost	Officers o Radio men o Unlicensed 3				
48.	No.passgrs. & others lost	Passgrs. O Others O				
49.	Total casualties	Injured 8 Lost 3				
50.	Persons lost by (Specify)	Drowning o Fire o Shell or Torp. 3				
		Other causes o				
51.	Total rescued	Gun crew O Officers & Radio Oprs. /				
-		Unlicensed 35 Passgrs. O Others & Total 34				
52.	Persons saved by	Boats 34 Rafts o Floats o Suits o				
		Preservers o Other means o No aid O				
53.	Engineering watch below	No.on watch below 5 No.lost below 3				
54.	No.of lookouts	2 hoogs s'qing(.ds -				
55.	Any defective material	Denotinada anus Denotinada en 11 - 65				
	gedW V%	No W VS bebraces girls asW - VS				
56.	Any personnel fault	28. [Mas ship brought in				
Comments, Criticisms and Recommendations						

The comments, criticisms or recommendations of survivors with respect to safety of seamen and ships involved in war actions, are earnestly solicited by Headquarters in order that the fullest provision possible may be made for the safety of American ships and seamen.