

UNITED STATES COAST GUARD

Captain of the Port

San Francisco

RADIO SEALING REPORT

Date 10/26/42 Time of arrival 4:15A.M. Place San Francisco Bay

Vessel James T. McPherson Class Steamship Nationality American

Owners/Operators War Shipping Administration Master F. Gries

REPAIRS TO RADIO APPARATUS

The repairs to radio apparatus are necessary as follows; _____

Master

DESCRIPTION OF RADIO APPARATUS

Transmitters: Senior radio operator George Willett

Number 1 :: Type # 150-AY Manufactured by Federal Telegraph Co. Power 200 W.

Frequency range 350 - 500 Kcs. Calibrated to 355, 375, 400, 454, 500 Kcs.

Number 2 :: Type # _____ Manufactured by _____ Power _____

Frequency range _____ Calibrated to _____

Emergency : Type # 150-AY Manufactured by Federal Telegraph Co. Power 50 W.

Frequency range 350 - 500 Kcs. Calibrated to 355, 375, 400, 454, 500 Kcs.

Lifeboat :: Type # _____ Manufactured by _____ Power _____

Frequency range _____ Calibrated to _____

Receivers: Type # _____ Manufactured by _____ Frequency range _____ Location _____

Number 1 ; 128-AX Federal Telegraph Co. 15 - 650 Kcs. Radio Room

Number 2 ; 123-BX Federal Telegraph Co. 350 - 550 Kcs. Radio Room

Number 3 ; _____

Number 4 ; _____

Lifeboat ; _____

Direction Finder; Std. Arrow Bludworth 270 - 520 Kcs. Chart Room

Auto - Alarm ; 101-B Federal Telegraph Co. Radio Room

(Over)

Signal Apparatus:

Brief description Blinker & International flags

Brief description of sealing operations: Seals intact from last previous port.

I hereby certify that I have, in accordance with orders of the District Coast Guard Officer, 12th Naval District, sealed the radio apparatus of the above-named vessel. The seals used in sealing the apparatus are _____

and are not serially numbered.

Note any deficiencies observed or other remarks:

Joseph A. Beekman
Joseph A. Beekman
Signature

Sea. 1/c
Rank or rating

Captain of the Port
San Francisco, California
(Date)

1. Forwarded for the information of the Commandant, U. S. Coast Guard.

W.P. Malloy
Signature W.P. Malloy

Rank Lt. (jg)
By direction of the Captain
of the Port.
San Francisco.

Copy to: Port Director
12th Naval District
Room 447 - Federal Office Building
Federal Communications Commission
328 Custom House