UNITED STATES COAST GUARD Captain of the Port San Francisco

Date <u>8/2/43</u> Time of	arrival New Sh	ip Place San Fran	cisco
Vessel John Evans	Class Steams	ship Nationality Am	erican
Owners/Operators War Shipp			
	REPAIRS TO RADI		
The repairs to radio apparatus are necessary as follows;			
		and the second second	
			Master
	escription of RA	DEO APPARAUTS	
dransmittors:	and the second s	nior radio operator	W.D. Ross
Number 1 :: Type #ET-8024			
Frequency range 350-	-500 Kes. Cali	brated to355-375-40	0-410-425-454-468-
Number 2 :: Type #	Manufactured by		Power 500 Kcs.
Frequency range	Cali	brated to	
Emergency: Type #ET-8025	Manufactured by	R.C.A.	Power 40 W.
Frequency range 350	-500 Kes, Cali	brated to355-375-400	0-410-425-454-468-
Lifeboat :: Type #FT-8026	Manufactured by	R.C.A.	Power 5 W.
Frequency range 50	O Kes. Calil	prated to 500 Kcs.	
Receivers: Type #			
Number 1 ; AR-8510		14 - 650 Kes.	Radio Room
Number 2 1 C	R.C.A.	350 - 515 Res.	
Number 3; SLR-F	SCOTT	530-1600 %	Radio Room
Number 4; SLR-12-B	SCOTT	530-1600 & 5550-15650 Kcs	. Chart Room
Lifoboat ;			
Direction Finder; 106-B Fe	deral Telegrap	oh Co. 270 - 520	Kcs. Chart Room
Auto - Alarm ; AR-8601	R.C.A.		Radio Room

Signal Apparatus: Brief description Blinker & International flags. Brief description of sealing operations: Sealed by F.C.C. I hereby certify that I have, in accordance with orders of the District Coast Guard Officer, 12th Naval District, sealed the radio apparatus of the ... above-named vessel. The seals used in sealing the apparatus are and are not serially numbered. Note any deficiencies observed or other remarks: Renk or rating .. Captain of the Port Sen Francisco, California (Date) Forwarded for the information of the Commandant, U. S. Coast Guard. By direction of the Captain of the Port. San Francisco. Copy to: Port Director

Copy to: Port Director

12th Naval District

Room 447 - Federal Office Building
Federal Communications Commission,
328 Custom House