
## Declassified NA 63684

## REPORT ON U. S. MERCHANT VESSEL WAR ACTION CASUALTY

		Operator MOORE		
nfo	rmation furnished by MASTA	X. S.W. TENAMENT AS A MARKET IN S. S.W. TENAMENTAL	Date 21 SEPTEMBER 1944	34
INE NO.	QUESTIONS	VSNA ber carried PD _ Number used _ P		35
1	Year built and propulsion	Built 1942 bodastiA	Propulsion STERIY	38
2	Tonnage	Gross 7176	Net 3464 4374	78
3	Draft loaded (maximum allowed)	Fwd 27' 9"(M)	Art 27'08%	
4	Draft when attacked	Fwd 16'(M)	Rescued by and where	88
5	Cargo on board (any deck)	Nature BALLAST	Number of gun crew carried (military).	89
0	a Se boardonno	Officers		Gu
0	Voyage	From BAHIA, BRAZIL	Number presengers and others carried	13
	Were routing orders followed	110	Total on board.	42
8	ny criticism of orders	Officers	Number gun crew injured (military)	48
9	Weather at time of attack	Weather CLOVDY	Sea SLIGHT	T.F.
0	Was enemy sighted? When	Passengers	Number passengers and others injured.	45
1	Any friendly ships in sight	YES; CONVOY	Number gun erew lost (military)	16
2	Were navigation lights on	NO.	Number ship's area lost	
3	Date and time of attack	Date 3/9/49	Time 0306	48
4	Position	Latitude 07°11'N	Longitude 53°30 W	01
5	Nature of attack (Give data)	TORPEDOED		
6	Number of hits	/ SHI SHINGIG	Persons lost by (Specify)	08
7	Location of hits (Mark diagram)	I-AFT.	5 - P	
8	Effect of hits	EXTENSIVE DAMAGE		
9	as ship armed? What type	Unlicensed Passengers		
	Was armament used? State result	No liants of the stands		
		redTOarevrear1	Cargo NO	
1	Any explosions or fires*	Number on watch below quick	Engineering watch below	53
2	Was deck ruptured		Number of look-outs.	54.
	Did ship break in two		Any defective material	55
1	Was SOS sent	YES		NOTE
5	Ship's speed	Normal // When attacked	When abandoned	56
6	Time abandoned, sunk	Tibulidonod Lezzarza	Sunk	
7	Was ship reboarded	By whom HALF OF CREW DION'T ABANDOWNen		
8	Was ship brought in YES	How TOWED	Approximate damage EXTENSI	UE



\*Fill in this diagram to show attack hits, fires, etc.

THE PORT LIFE BORT

16-34271-1

## Indicate by star (\*) rafts, flores lassified NARA Projectic NAV 53684

LINE No.	QUESTIONS	GRAUD TRAOD WHIATE GRIVANSWERS			
29	Lifeboats	Number carried 4 Which used 3 PARTIBLY ABBUTONED			
30	Lifeboats	Number lost			
31	Life rafts	Number carried 4 Which used 6 brand lead 2 II Anabasana 3 ToT			
32	Life rafts	Number lost 2014 WHOW NEEDED			
33	Life floats	Number carried			
34	Life floats	Number lost How NOT WREDEY vd bade multiple distantial			
35	Lifesaving suits	Number carried 66 Number used 6			
36	Were boats, etc., attacked	Attacked Casualties 6			
37	Time in each boat, raft, etc	Boats -/-HR. Raft Float	I Ye		
	- Not - Not - Not - Not	Boat Raft Float	Z To		
38	Rescued by and where	By ALLIED SHIP Where AT SCENE	8 13		
39	Number of gun crew carried (military)	Officers Enlisted men	4 Da		
40	Number ship's crew carried	Officers & Radiomen / Unlicensed 33	0 8		
41	Number passengers and others carried	Passengers Others O	26. 9		
42	Total on board	58 23\ benoiled subtro gailuor ens			
43	Number gun crew injured (military)	Officers Enlisted men			
44	Number ship's crew injured	Officers Radiomen Unlicensed /	777 67		
45	Number passengers and others injured.	Passengers Others O	OTT MA		
46	Number gun crew lost (military)	Officers C Enlisted men C	12 We		
47	Number ship's crew lost	Officers Radiomen Unlicensed	13 Da		
48	Number passengers and others lost	Passengers Others O	St. GI		
49	Total casualties	Injured			
50	Persons lost by (Specify)	Drowning O Fire O Shell or torpedo O	17. GE		
		Other causes			
51	Total rescued	Gun crew	18 To		
		Gun crew Officers Radio operators Unlicensed 33 Passengers Others Total 51  Boats 33 Rafts O Floats Suits O	To		
52	Persons saved by	Boats 33 Rafts 6 Floats Suits 6	ill oc		
		Preservers Other means No aid A	21 An		
53	Engineering watch below	Number on watch below Number lost below Number lost below	22 Wa		
54	Number of look-outs	7			
55	Any defective material	YES; DOORS IN FIDLEY on two			
870		ip's speed Normal W.S. When etterled			
56	Any personnel fault	ne abandoned, sunk			
	Sunk West	20 CASA SA CARANTANA DEBUGINGON	777 750		

## COMMENTS, CRITICISMS, AND RECOMMENDATIONS

The comments, criticisms, or recommendations of survivors with respect to safety of seamen and ships involved in war actions are earnestly solicited by Headquarters in order that the fullest provision possible may be made for the safety of American ships and seamen.

u. s. GOVERNMENT PRINTING OFFICE 16-34271-1

NOTE O - AFTER THE TORPEDOING, THE "YARK HANNA" WAS DRIFTING, WHEN IT BECAME APPARENT THAT THE "MARK HANNA" MIGHT COLLIDE WITH THE "JAMES
SMITH"-ALSO TORPEDOED - THE MASTER ORDERED THOSE ASSIGNED TO
THE PORT LIFE BOATS TO LOWER THEM AND TO STAND BY TO REBURD
IN THE EVENT THE AFOREMENTIONED COLLISION LOVLD BE AVOIDED, THE
COLLISION WAS AVOIDED BUT THE TWO BOATS WENT ADRIFT-TO BE
PICKED UP LATER BY AN ESCORT VESSEL