(Feb. 1943) NCG 924d-1

## Declassified NARA Project: NW 63684


UNITED STATES COAST GUARD
REPORT ON U. S. MERCHANT VESSEL WAR ACTION CASUALTY

TO: Commandant, U. S. Coast Guard, Washington, D. C.

Ship M/S MELVIN H. BAKER Service OCEAN FREIGHT

Owner NATIONAL GYPSUM Co. Operator WATERMAN SS. Co.

In	fo. furnished by MASTER		Date 3 AUGUST 1944		
Line No. QUESTIONS		ANSWERS			
1.	Year built & propulsion	Built 19	119	Propulsion Di	ESEL
2.	Tonnage	Gross 49	99	Net 3/14	
3.	Draft loaded (max. allowed)	Fwd. 25'	3"(M)	Aft	
4.	Draft when attacked	Fwd. 25'.	3" (M)	Aft	0 01011 00
5.	Cargo on board (any deck)	Nature GE	NERAL	Tons	6825
6.	Voyage	From Bom	SAY	TO NEW YORK	VIA. CAPETOWN
7.	Were routing orders followed	YES		made And B	SS Recove
8.	Any criticism of orders	No	(-411)	or) being an word	ana -01 -02
9.	Weather at time of attack	Weather CL	OUDY	Sea SLIGHT	40, 10, ehl
10.	Was enemy sighted - (when)	YES; AFT	TER ATTI	ACK	AL To one
11.	Any friendly ships in sight	NO		bused at	Later Sh
12.	Were navigation lights on	NO	Imetiti	i bandul warn	mrs. ok . Eb
13.	Date and time of attack	Date 6/6/	142	Time 0246	A. No. abi
14.	Position	Lat. 210 4	1415	Long. 36°38	E
15.	Nature of attack (Give data)	TORPED	0	illa) took ware	mysell lawsym
16.	Number of hits	1	*	faci were ale	ing.out.Te
17.	Location of hits (Mark diagram)	I-AFT.	1-319	7 4 S	mag. 60 . 80
18.	Effect of hits	SANK SH	IP	is a full subset	18703   502
19.	Was ship armed (What type)	YES	- 1 No.	raede) An agent	1031011100
20.	Was armament used(State result)	NO			Lates (1a
21.	Any explosions or fires*	Ship NO		Cargo NO	1
22.	Was deck ruptured				W-258-11-20
23.	Did ship break in two	NO			
24.	Was SOS sent	NO.		otes assum and a	-
25.	Ship's speed	Normal /o			bandoned STOP.
26.	Time abandoned, sunk	Abandoned	(5 min.)	Sunk 0245 (	5 min.)
27.	Was ship reboarded	By whom	No	When	
28.	Was ship brought in	How	NO	Approx. damage	SUNK



\*Fill in this diagram
to show attack hits,
fires, etc.

## Declassified NARA Project: NW 63684

## Sheet 2 NCG 924d-1

Indicate by star (\*) rafts, floats or suits used as temporary refuge in water before rescue by lifeboats

Line N	QUESTIONS	ANSWERS				
29.	Lifeboats	No.carried 2 Which used2				
30.	Lifeboats	No.lost & How &				
31.	Life rafts	No.carried 4 Which used / *				
32.	Life rafts	No.lost 3 How NOT NEEDED				
33.	Life floats	No.carried / Which used 6				
34.	Life floats	No.lost O How O				
35.	Lifesaving suits	No.carried o No.used O				
36.	Were boats, etc. attacked	Attacked No Casualties o				
37.	Time in each boat, raft etc. 2	Boats - 10 HRS. Raft Float				
<b>ESSATTED</b>	THE MAN WAY OF THE PARTY OF	Boat Raft Float				
38.	Rescued by & where	By ALLIED SHIP Where 21°53'S, 36°38'E				
39.	No.gun crew carried (military)	Officers / Enlisted men 5				
40.	No. ship's crew carried	Officers & Radio men / Unlicensed 25				
41.	No.passgrs. & others carried	Passgrs. 8 Others O				
42.	Total on board	48 CM sauta et selda vilgeld val .ii				
43.	No.gun crew injured (military)	Officers o Enlisted men o				
44.	No.ship's crew injured	Officers o Radio men O Unlicensed O				
45.	No.passgrs. & others injured	Passgrs. O Others o				
46.	No.gun crew lost(military)	Officers 6 Enlisted men 6				
47.	No.ship's crew lost	Officers O Radio men O Unlicensed O				
48.	No.passgrs. & others lost	Passgrs. 6 Others 0				
49.	Total casualties	Injured O Lost O				
50.	Persons lost by (Specify)	Drowning o Fire o Shell or Torp.				
	3	Other causes o				
51.	Total rescued	Gun crew 6 Officers 8 Radio Oprs./				
		Unlicensed 35 Passgrs. 8 Others o Total 48				
52.	Persons saved by	Boats 48 Rafts O Floats O Suits O				
_		Preservers O Other means O No aid O				
53.	Engineering watch below	No.on watch below 2 No.lost below 0				
	No.of lookouts	3				
55.	Any defective material	bebracder gids sall .TS				
	500	No man and a serious s				
56.	Any personnel fault	NO				
Comments, Criticisms and Recommendations						

The comments, criticisms or recommendations of survivors with respect to safety of seamen and ships involved in war actions, are earnestly solicited by Headquarters in order that the fullest provision possible may be made for the safety of American ships and seamen.