

TIME	DATE	ACTIVITY
		Vessel reports 26 inch crack in deck, repair survey requested on arrival Guam - ETA 3/20
0500Z	3/22/66	Arr Guam - ETD for S.F. 4/11 ¹⁵ (NWS Concord)
2012Z	4/5	Dep " ETA S.F. 4/18
1650	4/19	ARRIVED SAN FRANCISCO
1805	4/19	DOCKED NSC-E
2009	4/19	SHIPPED TO Pier 64-5
0001	4/23	COMMENCED VOYAGE NSA 4/MATSON 4/11
1719	4/23	ARR. NWS CONCORD to load // ETD WESTBOUND 5/3
1300	5/3	DELAYED DUE TO RADAR REPAIRS
1305	5/3	Departed Concord Westbound, Short One Third Mile ETA Buckner Bay 5/19, ETD FOR Pusan 6/3
0000Z	5/19	ARRIVED BUCKNER BAY
1312Z	5/27	DEPARTED " " ETA. S.F. 6/11
1400	6/9	ARR. S.F. to DRY DOCK + REPAIR

