

NAVCG 2724
U. S. COAST GUARD
Aug. 1943

CAPTAIN OF THE PORT
REPORT ON
CONTINUOUS PROTECTION OF VESSELS IN PORT

* * * * *

Ship's Name **S/S MARJORY** Nationality **American**

Date of inspection **6 Aug. 1944** Time **1230**

Describe cargo if combustible

.....

Deck officer in charge Name **GARRIL S. MASON (Ch. Mate)**

Address **402 Ester Ave., Baltimore Md.**

Engine Room officer in charge Name **Basile E. Fore**

Address **P.O. Box # 145, Andrew, So. Car.**

GUARDS

Gangway guard was stationed: On Board **Yes** .. At Dock Neither

Was gangway guard alert? Yes **Yes** .. No

Was roving guard alert? Yes No

Were fire guards present during "hot work"? Yes No

Were other established precautions taken? Yes No

In working combustible cargo other than inflammable, was cargo guard stationed in ship's hold? Yes No

Coast Guard explosives loading detail : Number officers Men

Name of guarding agency employed **Sp. Deputy Sheriff**

Number of COTP guards **One** Position assigned **Gangway**

Number of Vol. P. S. Guards **None** ... Position assigned

Are signs posted
Have adequate

MANNING

Licensed personnel actually on duty and alert:

Deck Yes .. **Yes** No

Engine Room Yes .. **Yes** No

Number of crew members available for duty ... **Two for each**

BOARDING REQUIREMENTS

Coast Guard Identification Card Yes **Yes** No

Pass or evidence thereof Yes **Yes** No

Showing of legitimate reason Yes **Yes** No

MOBILITY

Is ship's jacket gear engaged? Yes No **No**

Is fire pump available for immediate use? Yes .. **Yes** ... No

Vessel is with ~~without~~ own electric power.

MOORING AND TOWING LINES

Are axes conveniently available? Fore.. **Yes**. Aft **Yes**

Are emergency towing lines available? Fore .. **Yes** Aft **Yes**

Are towing lines rigged for use by tug? Yes **Yes** No

LIGHTING

During hours of darkness the following areas are lighted (Answer Yes or No):

Main Deck .. **Yes** ... Offshore side ... **Yes** ... Over the Stern .. **Yes** Alleyways **Yes**

Deck of barges and top of house lighters **No. barges worked**

SMOKING

Are signs posted designating smoking areas? Yes **Yes**..... No

Have adequate "No Smoking" signs been posted? Yes **Yes**..... No

COMMUNICATION

Do watchmen and officers in charge know location of:

Fire apparatus Yes ..**Yes**... No

Fire alarm boxes Yes ..**Yes**... No

Telephones Yes ..**Yes**... No

GENERAL

Are licensed personnel alert? **Yes**.....

Are adequate hoses available? **Yes**.....

Is inflammable rubbish on board? ... **No**.....

Is the emergency fuel pump shut-off in working order? **Yes**.....

Is galley clean and free of combustibles? **Yes**.....

Any evidence of "makeshift" electric wiring?..... **No**.....

Has oil or grease been found in bilges? **No**.....

Are general port security posters prominently displayed on board? .. **Yes**...

Have foreign language posters been distributed? ... **Yes**.....

DISTRIBUTION:


Captain of the Port

Captain of the Port of Destination

District Coast Guard Intelligence Office

NOTE: Make a brief summary if inspection on the reverse side noting deficiencies and recommendations.

[Dotted lines for writing]


J. I. Glover, Lieut. (jg) USCG
In charge of Ship inspection detail